



NEW MUST-SEE SOLUTIONS

OUR LATEST INNOVATIONS THAT
SERVICE PROFESSIONALS NEED TO KNOW ABOUT

Metal Exterior Door Handle

UPGRADED SOLUTION | SEAMLESS REPLACEMENT



79100M (Rear Left)
Chevrolet 2007-00, GMC 2007-00



PROBLEM:


The original exterior door handles on certain Chevy and GMC trucks often break because they're made of plastic.

FIX:

This Dorman OE FIX replacement matches the fit and appearance of the factory handle but is upgraded with metal components for greater durability.

Diesel Exhaust Fluid (DEF) Heater

AFTERMARKET FIRST | NOW WITH DOMESTIC AND GERMAN VEHICLE COVERAGE



904-375
Mercedes-Benz 2015-07

**25% THICKER CASING
ON HEATER ELEMENT
HELPS REDUCE FAILURE
FROM FLUID INTRUSION**

OEM

PROBLEM:

The factory DEF heater element on certain Mercedes-Benz diesel engine-powered vehicles often fails from fluid intrusion.

FIX:

Dorman's OE FIX DEF heater features a heater element casing that's 25% thicker than the original part to help reduce failure from fluid intrusion.

Parking Brake Cable Adjuster

AFTERMARKET FIRST



926-284

Dodge 2008-94, Jeep 2006-98, Ram 2021-13

- Direct replacement for the original equipment part that restores proper function to a corroded parking brake cable adjuster
- Must pass strict material and torque testing to ensure durable service
- Enables parking brake operation by equalizing cable tension

Control Arm Bolt

AFTERMARKET FIRST



926-339

Lexus 2018-03, Toyota 2018-03

- This replacement upper control arm bolt simplifies suspension repairs when the original control arm bolt is corroded, stripped or broken
- Hardened steel construction that matches the fit and function of the original bolt
- Has undergone material testing and validation to ensure reliable service life



Pre-Pressed Axles

TIME-SAVING SOLUTIONS | **NOW 12 PARTS AVAILABLE**



926-143 (Rear Left) | 926-144 (Rear Right)
Toyota Tundra 2016-07 - V8 4.6L



PROBLEM:

On many late-model Toyota Tundra pickup trucks, without special equipment it's easy to damage the rear wheel bearing when pressing out the old bearing or pressing in the new one.

FIX:

Dorman's OE FIX pre-pressed axles include all the major components needed for a complete repair, pre-assembled and ready to install right out of the box, with no shop press or specialized equipment required.

Dust Shields

AFTERMARKET FIRST



- Protect the braking system from debris and corrosive weather conditions with this rust-resistant brake dust shield for over a million Chevrolet and GMC pickup trucks
- Pair of direct replacement that matches the fit and function of an original part that is highly prone to deterioration

947-018

Chevrolet 2007-05 (Rear), GMC 2007-05 (Rear)

Diesel Exhaust Fluid (DEF) Pump

RELIABLE REPLACEMENT



904-608

Mercedes-Benz 2018-07, Volkswagen 2014-07

- Quality-tested, direct replacement for the original DEF pump that offers factory pump function at a competitive price
- Plug-and-play installation for a seamless and professional replacement

Infotainment Screen

AFTERMARKET FIRST



601-710

Cadillac ATS 2018-15, Cadillac CTS 2019-15,
Cadillac SRX 2016-13, Cadillac XTS 2019-16

PROBLEM:

When the infotainment touchscreen on certain CUE-equipped Cadillac models cracks and delaminates, the dealer only offers a complete infotainment module to fix it.

FIX:

Dorman's OE FIX replacement screen allows the damaged screen to be replaced, rather than the entire module assembly.

Blind Spot Module

AFTERMARKET FIRST



601-289

Ford Edge 2018-17, Ford Explorer 2018-17,
Ford Mustang 2018, Lincoln MKX 2018-16

- This aftermarket-exclusive blind spot detection (or object sensor) module is a reliable replacement for the original module that has failed due to damage or electrical malfunction
- Engineered to match the fit and function of the factory module on nearly a million late-model Ford and Lincoln vehicles in operation today