




NEW MUST-SEE SOLUTIONS

OUR LATEST INNOVATIONS THAT
SERVICE PROFESSIONALS NEED TO KNOW ABOUT

Plastic Oil Drain Plug

IMPROVED DESIGN | **STOP THE SPLASH**

**EASY-TWIST
OPEN AND CLOSE
FOR SERVICE**



**NO-MESS
OIL SPOUT
DRAINS
DOWNWARD**

097-826HPD

Ford 2021-15, Ford 2012-11, Lincoln 2021-16



097-826HPD

(sold in individual retail blister packaging)



PROBLEM:

Original equipment drain plugs on over 2 million late-model Ford and Lincoln vehicles cause oil splashing on chassis components during oil changes.

FIX:


This Dorman OE FIX plug is made of high-temperature plastic and features a downward-facing drain hole and convenient twist tabs for easy, spill-free servicing.

Wheel Nuts

UPGRADED DESIGN

**THIN DECORATIVE
OVERLAY**

STEEL WHEEL NUT



**SOLID CARBON STEEL
WITH CHROME FINISH**

**TWO-PIECE OE
DESIGN**



**SOLID OE FIX™
DESIGN**



611-584

Ford Explorer 2019-11, Ford Police Interceptor Utility 2018-14



PROBLEM:

The original lug nut on more than 1.5 million Ford Explorers and Police Interceptor Utility vehicles has a failure-prone two-piece design that makes rust common and repair difficult.

FIX:

This Dorman OE FIX replacement has a one-piece, carbon steel design to prevent future problems.

Ceramic-Coated Exhaust Manifold Kit

MORE DURABLE REPLACEMENT SOLUTION | **PREMIUM CERAMIC COATING FOR GREATER DURABILITY**



DORMAN

OE

**SALT SPRAY TESTS ON
ORIGINAL EQUIPMENT EXHAUST
MANIFOLDS VS. DORMAN
CERAMIC-COATED MANIFOLDS.**

OE manifolds were rust-covered after just 24 hours. Dorman's ceramic-coated exhaust manifolds had less than 15 percent rust on surfaces after 72 hours.

- Dorman's heat- and corrosion-resistant, high-performance ceramic coating provides hardworking commercial fleets and work trucks a more durable solution for replacement exhaust manifolds
- Includes gaskets and hardware for a hassle-free installation on vehicles powered or repowered with General Motors LS engines
- First in Dorman's new ceramic-coated manifold lineup, with expanding coverage for many popular engines coming soon

NOW INCLUDES MANIFOLD TO HEAD MOUNTING HARDWARE!

674-858XD (Right) | 674-859XD (Left)

Chevrolet 2007-03, GMC 2007-03, Isuzu 2007-03, Workhorse 2007-04, Workhorse Custom Chassis 2007-04






NEW MUST-SEE SOLUTIONS

OUR LATEST INNOVATIONS THAT
SERVICE PROFESSIONALS NEED TO KNOW ABOUT

Transmission Torque Converter Clutch Solenoid

AFTERMARKET EXCLUSIVE



926-378

Chrysler 2016-07, Dodge 2020-08, Ram 2021-12

- Exclusive direct replacement solenoid for over 4 million popular Chrysler, Dodge and Ram vehicles
- Reliable solution to clear diagnostic trouble code and restore proper torque converter function

Wiper Motor And Transmission Assembly

COMPLETE REPAIR SOLUTION



602-445AS

Toyota Corolla 2013-09

- Complete wiper motor and transmission assembly for over 1 million Toyota Corollas in operation
- 100% new, all-in-one solution to repair the entire assembly right the first time and save time, money and headaches

Blind Spot Detection Module

EXPANDED COVERAGE



601-285

Ford Escape 2018-17

- Direct replacement for original blind spot detection module
- Restores proper function of Ford BLIS and CTA system and clear fault messages

HD Diesel Fuel Filter Housing

AFTERMARKET EXCLUSIVE




904-558

Chevrolet Silverado 2500 HD/3500 2004-01,
GMC Sierra 3500 2004-01

- Ready to install with all necessary hardware for a complete repair
- Eliminates fuel leaks from a damaged coupling and fixes rough-start and no-start conditions
- Tested to ensure a trouble-free fit and installation

Cruise Control Distance Sensor

REPLACES FAILURE-PRONE ORIGINAL



601-725

Ford F-150 2020-15



601-733

Ford Escape 2020, Ford Explorer 2020,
Lincoln Aviator 2020, Lincoln Corsair 2020

- Direct replacement for failure-prone factory sensor on over 3 million Ford and Lincoln pickups and SUVs
- Clears fault code and restores adaptive cruise control distance detection function to original equipment standards

